

60cm Slide Out RANGEHOOD

PRODUCT CODE: **ES602SS2**



FEATURES:

- + Stainless steel front fascia
- + 2 speed extraction
- + Twin motors
- + 440m³/hr extraction capacity
- + Automatic light function
- + 1.5w LED Light
- + Integrated front panel
- + Dishwasher safe cassette filter
- + Non visible controls system
- + New smooth railing system
- + Decibel rating 49-58 dBA
- + 120mm Airflow outlet

2 SPEED EXTRACTION

This rangehood provides the option of 2 different speed levels ensuring you have the option to use your rangehood at a low or high level of operation.

DISHWASHER SAFE CASSETTE FILTERS

The cassette filters can be placed in a dishwasher for easy cleaning and can easily be removed, re-connected from the rangehood.

HIGH EXTRACTION CAPACITY

The extraction capacity of 440m³/hr provides strength and power through the use of twin motors.

DECIBEL RATING

48-56 dBA
Decibel rating is greatly improved through the use of semi rigid or ducted extraction flue kit.

Electrical Requirements

Rangehood is supplied with 10amp cord & plug.

Decibel Rating

48-56 dBA

Available Ventilation Kits

RHKE65EU	Wall – Eave vent kit
RHKMR65EU	Universal metal roof kit (includes flashing)
RHKTR65EU	Universal tile roof kit (includes flashing)

Carbon Filter

CF110 (requires 2)

Barcode

9347726027821



eurocooking



Warranty

HELPFUL TIPS

- + Leave your rangehood on for 15 minutes after the cooking of the food to remove all odors, steam etc.
- + The dishwasher-safe cassette filters need to be cleaned after approximately 2 months of standard operation
- + It is recommended that the rangehood be installed between 650mm and 750mm above the cooktop
- + It is also recommended that fumes from the rangehood be ducted out into the atmosphere.
- + Turn off the rangehood before attempting to clean

INSTALLATION

Installation is recommended by a qualified installer, please refer to the product manual for full installation instructions.

FILTER CLEANING INFORMATION

Cassette mesh filter: Requires cleaning monthly. This will ensure no interruptions with airflow operation.

